



ADAS Functionality - Filled Report

Name: Jessica Moreno

Designation: ADAS Technician

Vehicle No.: ADAS-FLT-2025

Date: 2025-05-14

Odometer: 65,700 mi

Sr	ADAS Inspection Item	Status	Remarks
1	Test lane departure warning/prevention function 2	OK	No issue
2	Verify backup camera system function 1	OK	No issue
3	Ensure driver monitoring systems function 5	OK	No issue
4	Check driver monitoring systems function 4	OK	No issue
5	Verify parking assistance systems function 7	OK	No issue
6	Verify lane departure warning/prevention function 1	OK	No issue
7	Evaluate adas calibration status function 6	OK	No issue
8	Ensure forward collision warning/mitigation function 5	OK	No issue
9	Ensure automatic emergency braking function 5	OK	No issue
10	Verify driver monitoring systems function 1	OK	No issue
11	Evaluate forward collision warning/mitigation function 6	OK	No issue
12	Ensure blind spot monitoring function 5	OK	No issue
13	Evaluate traffic sign recognition function 6	OK	No issue
14	Check parking assistance systems function 4	OK	No issue
15	Inspect lane departure warning/prevention function 3	OK	No issue

Signature: _____

Barcode: |||||